



# Queen Mary Hospital (QMH) Redevelopment Project - Phase I


# Presentation for SDC Meetings on 13 Nov 2014




### Agenda

- Background
- SSQ Project Progress
- Visit to QMH

#### **Proposed Project Scope of QMH Redevelopment Project Phase I**



#### Proposed Project Scope of QMH Redevelopment Project Phase I



#### Redevelopment of QMH (Phase 1) – Preparatory Works <u>Converted SSQ Building – Before & After</u>




Before

After

### **SSQ Project Progress**

#### **Project sections**



7/17


The P

T

1

1

#### Redevelopment of QMH (Phase 1) – Preparatory Works <u>Site Progress Photos</u>





Entrance to SSQ

### **Section A (Conversion Works)**



Aerial View of SSQ



Installation of derrick at L23 in progress



Site Gantry



Fabrication of steel beam in progress



Installation of metal scaffolding for demolition

### Section B (Road B Widening & Retaining Wall Works)



Road B current condition (1)





Road B current condition (2)

Geotechnical investigation works

#### Section C (Road D Widening & Water Diversion)



Road D works area



Reinforcement for Retaining Wall Footing



Excavation to the Top of Rock Head



Rock Hacking at Mass Concrete Wall 11/17

#### Redevelopment of QMH (Stage 1) – Preparatory Works <u>Site Progress Photos</u>



Noise barrier for Road D works


# Section D (Link Bridge – Utility Survey & Diversion)



General View at Link Bridge Site Area



Re-surfacing for Double Deck Parking




13/17

General Aerial View at Link Bridge Site Area

# Hospital Visit by Southern District Councillors 9 Oct 2014



### Waiting Area for Green Mini-bus (GMB) Route 63



The existing waiting area for GMB route no. 63 is on the ground floor of Block S.

There is a lack of adequate shelter at this waiting area, causing considerable inconvenience and discomfort to the passengers in rainy days and summertime. Members suggested erecting a half length anti-rain louver to provide adequate shelter and allow free airflow at the same time



#### Insufficient Space for Wheelchair Users at the Taxi Stand



#### Limitations & Constraints:

- Inadequate space for the boarding and alighting of passengers on wheelchair
- No dedicated queuing lane for passengers on wheelchair
- Queuing lane for passengers interrupted by columns aggravates the situation
- Security staff for on-site traffic control only feasible during peak hours due to manpower constraints

# Visit to SSQ and Road B



